

SVE BULLETIN

SPECIAL VEHICLE ENGINEERING – BODY BUILDERS ADVISORY SERVICE

E-Mail via Website: www.FordBBAS.com (click "Contact Us")

Toll-free: (877) 840-4338

QVM BULLETIN: Q-287R2

DATE: 24 / JAN / 2022

DIESEL FUEL CONDITIONING MODULE RELOCATION SERVICE KIT

REVISION	UPDATE	REVISION DATE
Q-287R2	COMBINED 2016 TO CURRENT MY INTO THIS BULLETIN	19JAN2022
Q-287R2	ADDED 2021 MODEL YEAR SERVICE PART	28JUL2020
Q-287R1	UPDATED SERVICE PART INFORMATION	30APR2020
Q-287	INITIAL RELEASE	12APR2020

MODEL(S) AFFECTED:

All 2021 F-650 / 750 Vehicles (See Page 1) and 2016 - 2019MY F-650 / 750 (See Page 2) Equipped with Diesel Engines

ISSUE / DESCRIPTION:

In some applications, the **Diesel Fuel Conditioning Module (DFCM)** needs to be relocated to facilitate installation of a PTO accessory to take full advantage of available engine HP and Torque.

Ford Motor Company has developed a Service Kit which relocates the **DFCM** to provide a clean PTO driveline routing.


2021MY+ F-650 / 750:

The kit service part number for the 2021 Model Year is: **MC4Z-9S317-A**

Service Kit Contents (MC4Z-9S317-A):

- DFCM Relocation Bracket
- Parking Brake/Fuel Line Retention Bracket
- Replacement Fuel Supply Lines
- Additional Hardware and Installation Instructions

Service Kit MC4Z-9S317-A is available through your authorized Ford Service location.




2016 - 2019MY F-650 / 750:

The kit service part number for the 2016 through 2019 Model Year is: **JC4Z-9S317-C**

Service Kit Contents (JC4Z-9S317-C):

- DFCM/TCM Relocation Bracket
- Parking Brake/Fuel Line Retention Bracket
- Replacement Fuel Supply Lines
- Additional Hardware and Installation Instructions

Service Kit JC4Z-9S317-C is available through your authorized Ford Service location.



Refer to the Body Builder Layout Book for additional guidelines and recommendations. If you have any questions, please contact the [Ford Body Builders Advisory Service](#) as shown in the header of this bulletin.